

# WOLF CREEK

NUCLEAR OPERATING CORPORATION

Clay C. Warren  
Chief Operating Officer

December 23, 1997  
WO 97-0141

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Mail Station P1-137  
Washington, D. C. 20555


Subject: Docket No. 50-482: Licensee Event Report 97-024-00

Gentlemen:

The attached Licensee Event Report (LER) 97-024-00 is being submitted pursuant to 10 CFR 50.73(a)(2)(iv) concerning Engineered Safety Features and Reactor Protection System actuations. The actuations were caused by a spike on the Ex-Core Neutron Monitoring System Nuclear Instrument NI-35 Intermediate Range Channel.

If you should have any questions regarding this submittal, please contact me at (316) 364-8831 Extension 4485, or Mr. Michael J. Angus at extension 4077.

Very truly yours,



Clay C. Warren

CCW/jad

Attachment

cc: W. D. Johnson (NRC), w/a  
E. W. Merschoff (NRC), w/a  
J. F. Ringwald (NRC), w/a  
K. M. Thomas (NRC), w/a

9801020148 971223  
PDR ADOCK 05000482  
S PDR

IE221



# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9801020148 DOC.DATE: 97/12/23 NOTARIZED: NO DOCKET #  
FACIL:STN-50-482 Wolf Creek Generating Station, Wolf Creek Nuclear 05000482  
AUTH.NAME AUTHOR AFFILIATION  
WARREN,C.C. Wolf Creek Nuclear Operating Corp.  
RECIP.NAME RECIPIENT AFFILIATION  
Document Control Branch (Document Control Desk)

SUBJECT: **Forwards LER 97-024-00** re ESFs & RPS actuations which were caused by spike on ex-core neutron monitoring sys nuclear instrument NI-35 intermediate range channel.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1 + 4  
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:Standardized Plant.

05000482

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD4-2 PD	1 1	THOMAS,K	1 1
INTERNAL:	AEOD/SPD/RAB	2 2	AEOD/SPD/RRAB	1 1
	FILE CENTER	1 1	NRR/DE/ECGB	1 1
	NRR/DE/EELB	1 1	NRR/DE/EMEB	1 1
	NRR/DRCH/HHFB	1 1	NRR/DRCH/HICB	1 1
	NRR/DRCH/HOLB	1 1	NRR/DRCH/HQMB	1 1
	NRR/DRPM/PECB	1 1	NRR/DSSA/SPLB	1 1
	NRR/DSSA/SRXB	1 1	RES/DET/EIB	1 1
	RGN4 FILE 01	1 1		
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE,J H	1 1
	NOAC POORE,W.	1 1	NOAC QUEENER,DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24

1130

NRC FORM 366  
(5-92)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104  
EXPIRES 5/31/95**LICENSEE EVENT REPORT (LER)**

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

WOLF CREEK GENERATING STATION

DOCKET NUMBER (2)

05000482

PAGE (3)

1 OF 4

TITLE (4)

Engineered Safety Features and Reactor Protection System Actuations Due to a Spike on the Ex-Core Neutron Monitoring System (SE) Nuclear Instrument NI-35 Intermediate Range (IR) Channel.

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV. NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
11	29	97	97	24	00	12	23	97	FACILITY NAME	DOCKET NUMBER

OPERATING MODE (9)		MODE 1		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)							
POWER	LEVEL (10)	007 percent		20.402(b)		20.405(c)	X	50.73(a)(2)(iv)		73.71(b)	
				20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)	
				20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)		OTHER	
				20.405(a)(1)(iii)		50.73(a)(2)(i)		50.73(a)(2)(viii)(A)		VOLUNTARY	
				20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)			
				20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x)			

LICENSEE CONTACT FOR THIS LER (12)

NAME

Michael J. Angus  
Manager, Licensing and Corrective Action

TELEPHONE NUMBER (Include Area Code)

316-364-8831 Extension-4077

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES				X NO		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (16):

On November 29, 1997, at 14:37 Central Standard Time a reactor trip occurred at the Wolf Creek Generating Station (WCGS). The plant was in mode one, at seven percent power, at the time of the trip. The Engineered Safety Features (ESF) and Reactor Protection System (RPS) performed as required. The automatic actuation of the reactor trip occurred as expected, with all rods inserting fully.

Subsequent investigation revealed that the reactor trip was caused by a spike on the Ex-Core Neutron Monitoring System (SE) Nuclear Instrument NI-35 Intermediate Range (IR) Channel. The spike exceeded the Intermediate Range High Flux trip setpoint of the current equivalent of twenty-five percent Rated Thermal Power (RTP). The cause of the spike is indeterminate. Based on the investigations performed, no anomalies have been identified that can be confirmed to have caused the IR High Flux trip. Corrective actions included stabilizing the plant, and investigating causes.

7801020149 971223  
PDR ADOCK 05000482  
S PDR



**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)		DOCKET NUMBER (2)		LER NUMBER (6)			PAGE (3)
				YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Wolf Creek Generating Station		05000482		97	024	00	2 OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**Plant Conditions Prior to the Event:**

MODE = 1

Reactor Coolant Pressure: 2239 psig

Reactor Power: 7 %

**Basis for Reportability:**

This report is submitted to document an automatic actuation of the Reactor Protection System (RPS) [JC] and the Engineered Safety Features (ESF) [JE]. This incident is reportable under 10 CFR 50.73(a)(2)(iv) which requires the Licensee to report any event or condition that resulted in manual or automatic actuation of an Engineered Safety Feature (ESF), including the Reactor Protection System (RPS).

**Description of Event:**

On November 29, 1997, at 14:37 Central Standard Time a reactor trip occurred at the Wolf Creek Generating Station (WCGS). The plant was in Mode one, seven percent power, at the time of the trip. Prior to the trip, the plant was stable with no rod motion or other reactivity manipulations in progress. The Reactor Protection System (RPS) and the Engineered Safety Features (ESF) performed as required. The automatic actuation of the reactor trip occurred as expected, with all rods inserting fully.

The plant was stabilized using the appropriate procedures, and Emergency Action Levels (EALs) were reviewed for any actions required. Performance Improvement Request (PIR) 97-3937 was issued to track and document investigations and corrective actions. The NRC Resident Inspectors were notified at 15:14 CST, and the RPS actuation was reported to the NRC on the ENS, as required by 10 CFR 50.72(b)(2).

Work Package 126224 was written to investigate the cause of the reactor trip and troubleshoot Intermediate Range (IR) channel N-35. Subsequent investigation revealed that the reactor trip was caused by a spike on the SE Nuclear Instrument NI-35 Intermediate Range (IR) Channel. The spike exceeded the Intermediate Range High Flux Trip setpoint of the current equivalent of twenty-five percent Rated Thermal Power (RTP).

Four items were immediately checked as potential causes of the spike, and subsequent trip:

1. **Plant Transients.** The spike was rapid enough that the NR-45 nuclear recorder trace is small and doesn't extend to the level that is equivalent to the trip setpoint. None of the independent, or redundant indications of reactor power (Power Range NIs, Post Accident NIs, and Delta-T's), showed any indication of a power transient occurring at the time of the IR trip, and no evolutions were occurring at the time that would have caused this type of transient.

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)		DOCKET NUMBER (2)		LER NUMBER (6)			PAGE (3)
				YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Wolf Creek Generating Station		05000482		97	024	00	3 OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

2. **Cycle 10 IR Trip Setpoints Calculation.** This calculation was reviewed and no errors were identified. The trip setpoints are similar in magnitude to the startup IR trip setpoints from Cycle 9.
3. **Cycle 10 IR Trip Setpoints Calibrations.** The calibration procedures used to implement the setpoints were reviewed. No anomalies were observed during the calibration, and correct values were used.
4. **Instrumentation problems.** The NI-35 spike was recorded on the SE NR-45 trend recorder, and captured as Nuclear Plant Information System (NPIS) archive data. Other than capturing the spike, the NPIS data does not yield much information because of the way the points are set to archive. Pre-trip trends on SE NR-45 and NPIS showed nothing abnormal with NI-35.

Details of the above investigation, as well as reviews of troubleshooting, instrumentation trending, power supply and amplifier status, the potential for ground faults and cable connector faults, compensation voltage and calibration checks, and potential detector aging, are documented in Performance Improvement Request (PIR) 97-3937. Based on the investigations performed, no anomalies have been identified that can be confirmed to have caused the IR High Flux trip.

Procedure AP 20-002, Revision 1, "Post Trip Review" was completed and approved November 30, 1997. Permission to restart the reactor was given at 16:50 CST on November 30, 1997. The plant entered Mode 1 at 23:02 CST on November 30, 1997.

**Root Cause:**

The root cause of this event was an intermittent positive spike on the Intermediate Range (IR) Channel NI-35. The amplitude of the spike exceeded the High Flux trip setpoint of current equivalent of twenty-five percent of RTP. The cause of the spike is indeterminate. Based on extensive investigation, no anomalies have been identified that can be confirmed to have caused this spike.

**Corrective Actions:**

- The plant was stabilized using the appropriate procedures, and Emergency Action Levels were reviewed for any actions required.
- Performance Improvement Request 97-3937 was issued to track and document investigations and corrective actions.
- Work Package 126224 was written to investigate the cause of the reactor trip and troubleshoot Intermediate Range channel NI-35.

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)		DOCKET NUMBER (2)		LER NUMBER (6)			PAGE (3)
				YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Wolf Creek Generating Station		05000482		97	024	00	4 OF 4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

- The NRC Resident Inspectors were notified at 15:14 CST, and the RPS actuation was reported to the NRC on the ENS, as required by 10 CFR 50.72(b)(2).

**Safety Significance:**

This event is not safety significant. The Intermediate Range detector functioned as designed to trip the reactor when the channel experienced a spike of greater than current equivalent of twenty-five percent Rated Thermal Power (RTP). The Intermediate Range High Flux Trip setpoint of current equivalent of twenty-five percent RTP is normally blocked when reactor power is above the P-10 permissive ( 2/4 Power Range channels greater than 10% power ), and the plant was stable at approximately 7% power. The purpose of the Intermediate Range High Flux Trip is to protect against a rapid power increase. The power range selected to the SE NR-45 nuclear recorder registered no increase in power indicating there wasn't an actual increase in power occurring in the core, and the trip was solely due to IR SE NI-35 spiking.

This event did not jeopardize the health and safety of the public. The Reactor Protection System and the Engineered Safety Features performed as required. The automatic actuation of the reactor trip occurred as expected, with all rods inserting fully.

**Other Previous Occurrences:**

A similar incidence of reactor trip and Engineered Safety Features actuation due to a spike on a channel of the power range instrumentation occurred on July 31, 1985. This event was due to an electrical spike on the NI-42 channel of the power range nuclear instrumentation. The channel spiked low, and the spike was caused by a faulty power supply. No other previous occurrences of reactor trip due to channel spikes of the power range instrumentation have been identified at WCGS.